



DEPARTMENT OF THE NAVY  
COMMANDER, REGIONAL SUPPORT GROUP, MAYPORT/  
SOUTHEAST REGIONAL MAINTENANCE CENTER  
MAYPORT, FLORIDA 32228-0057

4355  
Ser 220/134  
01 March 2005

Network Industries, Ltd.  
Chemical Division  
2241 Barraud Avenue  
Norfolk, VA 23504

Gentlemen:

In response to your submission dated 26 February 2005, Procedure 05-02, Chemically Clean Heat Exchangers with Blow-Out, has been reviewed for technical adequacy and compliance with NAVSEA Standard Item 009-09, FY-05 and is acceptable. This procedure or notification of intent to use, is required to be resubmitted upon award of a contract and or delivery order identifying the ship, system and work item.

The SUPERVISOR reserves the right to request changes to this procedure should it be determined that it produces a nonconforming product. The contractor shall notify the SUPERVISOR in writing of any change to this procedure.

Sincerely,

J. T. BARRINEAU  
Quality Assurance Manager  
By direction of the  
Commander Southeast Regional  
Maintenance Center, USN